

9 Dec 43 "Laverton – "Side gun cover of Ventura A59-1. which being test flown by S/L KM Kemp DFC, blew off pulling the dinghy release wire causing dinghy to burst out & strike tail, plane & port fin. Port tip of tailplane & port fin badly damaged. 1 AD A50.

Dec 43	"4 Ventura aircraft from 1 AD to 13 Sqn."	1 AD A50
28 Dec 43	"Ventura aircraft (Army type) B34. A59-1, 5 & 8 received."	13 Sqn A50
29 Dec 43	"Received 13 Sqn ex 1 AD."	Status card
8 Feb 44	F/O WW Birdsall    Can - Can <i>Nav &amp; Gunnery seaward 1hr 40mins - abandoned</i>	Bowden log 1
26 Feb 44	F/Lt GG Sprigg        Can - Can <i>Homing 1hr 10min Abandoned a/c U/S</i>	Bowden Log 1
As of 1 Apr 44	"All B34 aircraft have been grounded pending arrangements for complete overhaul."	WSR
28 Apr 44	"Ventura aircraft B34 A59-5, 7 & 1 departed to 2 AD on being issued off."	13 Sqn A50
28 Apr 44	"Received 2 AD ex 13 Sqn for report?."	Status card
May 44	"12 Ventura's received from 13 Sqn."	2 AD A50