I1 42	"12 Ainsuaft all	attad to data	Vantura 450 51 52 8 52"		12 San A50
July 43	·		Ventura A59-51, 52 & 53"		13 Sqn A50.
18 Aug 43	"Received 13 Sqn ex 2 AD."				Status Card
16 Aug 43	"Ventura aircraft A59-52 arrived."				13 Sqn A50
26-Sep-43	F/O AG Goudie	Canber	ra local? 0850-1035hrs	,	Whitlam log
28-Sep-43	F/O AG Goudie	Canber	ra local? 0850-1035hrs	•	Whitlam log
04-Oct-43	F/O AG Goudie	Canberra - Canberra	Circuits & landings1910-	2115hrs	Whitlam log
19 Oct 43	"Dual control set	returned 1 OTU."			Status Card
29-Oct-43	F/Lt GL Brown	Bundaberg - Canberra	0900-1300hrs	V	Vhitlam log
10 Nov 43 "Accident while low flying over land during low flying bombing exercise to seaward. Aircraft extensively damaged". Pilot F/Sgt M Boyd. NAA Ventura Accidents Pt 1.					
10 Nov 43	"Struck top of tree	e while low flying"		NAA Ventura Accide	nts Pt 1.
10 Nov 43 "Crashed Canberra. Airframe 10%M, Leading edge centre section Port 70%M, Port oil cooler & assembly 75%R, Remainder of A/C U." & "Aircraft to be repaired within unit, damaged oil cooler & assembly to be despatched to 7 AD for repair." Status Card					
10 Nov 43	Accident not reco	orded in 13 Sqn A50.			
12 Nov 43 "10/11/43CanberraA.F.A. Section 40 CONDUCT TO THE PREDUDICE OF GOOD ORDER & AIRFORCE DISCIPLINE in that he, without authority, carried out low flying practice in an unauthorised areaSeverely reprimanded." Boyd MT Service Record.					
13 Dec 43	"Ventura A59-52 (13 Sqn)) allocated to unit for 2-	40hr inspection."		14 RSU A50
5 Jan 44	"Ventura PV1 A59-52 issi	ued to 5 MG for 240hr i	inspection."		13 Sqn A50
7 Jan 44	"Received 14 RSU ex 13 Se	qn for 240hr & overhai	ul of engines".		Status Card
13 Mar 44	"Allotted 18RSU for compl	etion of repairs & then	19 Jun 44 2 AD for comple	etion of repairs."	Status Card
14 Mar 44	"A59-52 allotted to 18 RSU	I for completion of repo	urs."		14 RSU A50
18 Mar 44	"A59-52 allocated from 14	RSU for completion of	repairs."		18 RSU A50
12 May 45	"Received 11 CU - for use	of Senior Army Officers	3".		Status Card
8 Jun 45	S/L CE Cox(455) 11 Com I	Hollandia-Morotai Coi	nvey Army Survey Coy.(w	th A59-52) 1	1 Com A50
12 Jul 45	S/L CE Cox 11 Com Conve	ey Gen. Berryman Moro	otai-Manilla	1	1 Com A50
18 Aug 45 F	Lt RB Patrick 11 Com Co	onvey Lt Gen. Berryma	n Morotai-Manilla to meet	Jap envoys.	Patrick Log
22 Aug 45	F/Lt RB Patrick 11 Com M	Ianilla- Morotai		1	Patrick Log
23 Aug 45	F/Lt RB Patrick 11 Com M	Iorotai-Biak-Wakde		1	Patrick Log
24 Aug 45	F/Lt RB Patrick 11 Com W	/akde-Biak-Morotai		1	Patrick Log

13 Dec 45 "Received 2 AD" & placed into storage".

Status Card

Ref,

Ventura A59 [Accidents Part 1] A9845, 114, 650498.

NAA: Aircraft Status cards - Ventura A59-1 to A59-20, A59-50 to A59-104 A10297, BLOCK 376, 3046016.

NAA (11 Com) Communication Flights 5-13 Dec 42 - Oct 45 A9186 335

4 RSU A50 NAA: A9186, 372, 1359933.

BOYD Malcolm Thomas: Service Number - O34730: Date of Birth - 01/03/1923: Place of Birth - Camberwell, VIC: Conflict - WW2 - NAA: A12372, R/34730/H, 30724348.

WHITLAM, Edward Gough 423371: Faxed Log Book copy from Gough Whitlam 1991.